

(Operation Manual)

Digital speed meter

MODEL: SP-556 Series

Series name		Out	out			Input		Sensor Power	Power	Color	Cover	Туре	Function
SP-556													Preset output: NPN open collector(X2) Display: 7 segment red LED Input signal: NPN open collector Sensor power: DC12V 100mA Power source: AC100-240V Color: Gray Terminal block cover not attached
	GL												Display: 7 segment green LED
		P2											Preset output : PhotoMOS relay output($\times 2$)
	_		АΙ										Analog output: DC 4-20mA
			AV3										Analog output : DC 1-5V
			AV4										Analog output: DC 0-5V
			AV5										Analog output: DC 0-10V
				B*1									BCD output : NPN open collector All digits parallel
					BI*1								BCD input : NPN open collector All digits parallel
						F							Input : Voltage pulse input
						F2							Input: Current modulation pulse input(A)
						F2W							Input : Current modulation pulse input(A,B)
						V3							Input: Tacho-generator signal input AC 0.8V-80Vp-p
						Ν							Current modulation pulse input (A-input)
						L1							Input : Line receiver 1ch input (A • Ā)
							三						Input : High-speed input Response frequency : 0.01Hz-120kHz
						•		S24					Sensor power: DC24V 60mA
									DC *2				Power source: DC12-24V
										K			Color: Black
									•		С		Terminal block cover attached
												DM *3	Stationary type
												DM-CB *3	Stationary type (AC100V three-core cable)

^{*1 &}quot;B" option and "BI" option cannot be selected together.

^{*2} Optional "DC" is outside CE marking

^{*3} The meter is on subject of CE marking. But "DM" option is off the subject of CE marking.

Precautions

Please read this operation manual including the following precautions carefully to ensure safe use of your meter.



 $oldsymbol{\Lambda}$ $oldsymbol{Warning} \cdot \cdot \cdot$ The following cases that may cause death or serious injury.

- 1. Do not wire while power is supplied. There is a risk of electric shock and fire.
- 2. Do not touch the terminals while power is supplied. There is a risk of electric shock.
- 3. Do not disassemble or touch the inside of the product. There is a risk of electric shock and fire.
- 4. Do not use the product in places with flammable gas or ignitable substances.
- 5. Prepare the emergency stop or build a fail-safe system, etc. for when a product is break down or abnormality operating.



A Caution • • • That may cause Minor injury or Property damage.

- Use the product at the rated range power supply voltage and load.
- 2. Do not use the product at the following environment.
 - Where there is exposed to metal powder, dust, water, chemicals, oil, etc.
 - Where there is corrosive gas.
 - Outdoors or in direct sunshine.
 - Where condensation occurs.
 - Temperature and humidity outside the rated range.
 - Where there is vibration or impact.
- 3. Do not let metal powder, dust, water, chemicals or oil into the product. There is a risk of break down or fire.
- 4. Check periodically for defects and abnormalities.
- 5. If the product is break down, firing, emitting smoke, overheating, abnormal noise, etc. turn off the power immediately and stop using it.
- 6. Install a switch or circuit breaker where it can be operated immediately in an emergency, Then indicate that is a shutoff device.
- 7. Do not place the product and wiring near noise sources.
- 8. If there is a possibility of invasion the lightning surges, install countermeasure parts such as a lightning arrestor in outside.
- 9. It can be used almost at the same time as the power is turned on, but requires 30 minutes of power to meet all performance requirements.
- 10. When cleaning, wipe with a dry cloth. Do not use organic solvents such as benzine, thinner and alcohol.
- 1. If the waterproof packing is used in a deteriorated state, the waterproof and dustproof function will be impaired. Inspect and trade it periodically.
- 12. Use devices connected to each terminal of the terminal block, that is properly isolated from dangerous live parts.
- 13. Since this machine has no power-on switch, it will be in an operating state immediately after power supply impression.
 - On the side of your equipment that you equip the machine with, please be prepared to supply the switch and circuit breaker which adapted to IEC/EN60947-2 or
 - IEC/EN60947-3 standard in the position that you can operate immediately in emergency. Moreover, please specify that they are interrupting devices.
- 14. This machine is designed to be used with the panel mounted. Otherwise, the protection provided by the device may be impaired.
- 15. Use power code with the temperature rating 70 °C or more.

Product Description

This product is a panel mount meter that can measure Speed/Rotation/Flow rate/Ratio /Shot speed/Street time/Cycle timer/Stopwatch.

The preset output function of two points has been equipped normally. The preset output two points and the analogue signal and the BCD signal outputs can be added in the option. The option to which the preset setting value can be input from the outside by the BCD signal is prepared.

With the panel mounted, the front has been protected by grade IP66, dust and water resistant products.

Contents

1. About confirmation of an attachment, and a guaranteed period • • • • • 1
2. Specifications • • • • • • • • • • • • • • • • • • •
3. Mounting meter · · · · · · · · · · · · · · · · · · ·
4. Names and functions of components on front $\cdot \cdot \cdot$
5. Connecting terminal boards • • • • • • • • • • • • • • • • • • •
6. Construction of input circuit • • • • • • • • • • • • • • • • • • •
7. Dip switch • • • • • • • • • • • • • • • • • • •
8. The setting menu ••••••••••••••12-13
9. Initial setting values and initialization • • • • • • • • • • • • • • 14
10. Content and setting the each mode • • • • • • • • • • • • • • • 15-33
Operating method (the mode setting) Content of the each mode and set value [Mode No.0] Measuring types, Measurement unit, Display decimal point [Mode No.1] A-input: A-input: Setting of scaling data [Mode No.2] A-input: Exp.value, moving average, auto-zero time 23-24 [Mode No.3] B-input: B-input: Setting of scaling data [Mode No.4] B-input: Exp.value, moving average, auto-zero time 24 [Mode No.5] Deceleration ratio/Oven-length (tact pitch) setting 25 [Mode No.6] Sampling time 26 [Mode No.7] Hold-function setting, display blank, lowest digit display 27 [Mode No.8] OUT1: Preset output (open collector output) 28 [Mode No.9] OUT2: Preset output (open collector output) 29 [Mode No.A] OUT3: Preset output (photo MOS relay output, Option:P2) 29 [Mode No.b] OUT4: Preset output (photo MOS relay output, Option:P2) 30 [Mode No.c] Analog output: Setting of measurement choice and the output digit 31 [Mode No.d] Analog output: Setting of measurement choice and the output digit 31 [Mode No.E] BCD output setting (Option:B) 32 [Mode No.F] BCD input setting (Option:B) 33
11. Mode protect function ••••••••••••••34
12. Teaching function ••••••••••••••35
13. Calling up and modifying the preset value setting •••••••• 36
14. Adjusting the analog output (Option:Al/AV3-5) •••••••• 37
15. Adjusting the tacho-generator signal, sine wave signal input (Option : V,N) \cdot • 38
16. Connection diagram for BCD output (Option : B) • • • • • • • • • • • • • • • • • •
17. Connection diagram for BCD input (Option: BI) • • • • • • • • • • • • • • 40
18. External dimensions • • • • • • • • • • • • • • • • • • •
19. Stationary type (Option:DM) · · · · · · · · · · · · · · · · · · ·
20. About a noise countermeasure • • • • • • • • • • • • • • • • • • •
21. Troubleshooting •••••••44-45

1. About confirmation of an attachment and a guaranteed period

About confirmation of an attachment.

When you received as a product, please confirm whether it includes the following.

- (1) SP-556 (The chosen specification) •••••••1
- (3) Unit label (Attachment) •••••••••

If there are the mistaking parts and the missing parts, please inform a dealer or us. (There is a case that you don't attach by convenience.)

About a guaranteed period and a guaranteed area.

1. Guaranteed period

The period a product guarantees is 4 years from a delivered day.

2. Guaranteed area

If we trouble by responsibility in whole guaranteed period, it's repaired without charge at our factory. But if a product conflicted in the following matter, it isn't a guarantee target. Please understand.

- 1 Case of outside of the product specifications.
- 2 Case of User-conducted alterations and modifications of the unit.
- 3 Case of besides our responsibility.
- 4 Case of safekeeping and transportation beyond the product specification condition.
- (5) Case due to natural disaster and accident,

2. Specifications

(1) Standard specifications

	Item	Specifications
Measurement	Measuring types	Ratemeter (speed, rotation, flow rate,), differential rate, ratio, shot speed, passing time, cycletimer, stop watch
	Measuring system	Ratemeter (speed, rotation, flow rate.), differential rate, ratio, shot speed, passing time, cycletimer, stop watch periodic sampling operation 7segment red LED, 5digits, character height: 14mm (speed, rotation, flow rate, differential rate, ratio, passing time) ±0.05% rdg. ±1digit (at Sampling time for 0.5 second or more, per one inp (shot speed) ±0.1% rdg. ±1digit (in one measurement less than 100Hz) (cycletimer, stop watch) ±0.05% rdg. ±2ms ±1digit (in one measurement) 1×10-9 - 9999 -99999 1 1×10-9 -99999 1 1×10-9 -99999 1 1×10-9 -99999 1 1×10-9 -99999 1 1×10-9 -99999 1 1×10-1 1 1×10-9
	Display	7segment red LED, 5digits, character height: 14mm
	Measurement accuracy	±0.1% rdg. ±1digit (in one measurement less than 100Hz)
		$\pm 0.05\%$ rdg. ± 2 ms ± 1 digit (in one measurement)
	Scaling	1×10-9 -9999
_	Indication area -9999 - 99999 Overflow indication "99999" flashing	-9999 - 99999
Rate	Overflow indication	"99999" flashing or "-9999" flashing
Meter	Time unit	Per hour , per minute , per second
	Decimal point	10^{-1} , 10^{-2} , 10^{-3} , nothing
	Sampling time	Rate reading averaged by 0.1 sec – 99.9 sec
	Display blank	Blank the measured value
	Moving average	
	Auto zero time	
	Least significant digit	Real/Fixed at "0"/Fixed at "0" or "5"
	Reset	Reset the measurement with the front part reset key and RST input on the terminal block.
	Input signal	*Sensor conditions: • Residual voltage 2V or less when ON, leakage current 1.5mA or less when OFF
Sensor Input	Response freqency	MID: 0.01Hz~1kHz HI: 0.01Hz~10kHz
	Sensor power supply	DC+12V(±10%) 100mA
Reset input	Input method	
EXT	Input method	
Input	Operation selection	Hold, peak hold, bottom hold, reverse rotation input
	l	I .

	Output method	NPN open collector (×2)		
	Maximum rating	DC30V 50mA		
Preset	Comparison method	Compare the displayed value with the preset value		
output		Upper limit, lower limit (immediate), lower limit (delay)		
Odtpat	Output mode	Compare, hold, 1 shot		
	Judgment prohibition time	Stops preset output for 0 to 99 seconds after power is		
	oddsmortt prombition time	turned ON or after reset		
	Data backup	Save each setting value in FRAM		
		Write less than 100,000 times, keep about 10 years		
	Mode protect	Prohibit changing mode settings		
	Rated power	AC100-240V (-15% / +10%) 120mA max		
	supply voltage	50/60Hz (Allowable range : AC85-264V)		
	Power consumption	20 VA or less		
	Ambient temperature	0-50°C 30-80% RH (no condensation)		
	and humidity			
Others	External dimensions and weight	W96 × H48 × D130mm Approx 400g		
Others	Color	Gray		
	Case material	ABS resin (Terminal block : PBT black)		
	Protection class	IP66 (Front only)		
	Usage environment	Indoor use, Maximum altitude 2,000 m,		
	Osage environment	Overvoltage category II, Pollution degree 2		
	Low Voltage Directive	EN 61010-1		
	EMC	EN61326-1 EN55011 (Group1 ClassA), EN61000-4-2, EN61000-4-3, EN61000-4-4, EN61000-4-5, EN61000-4-6, EN61000-4-11		

(2) GL option

Display Display	7segment green LED, 5digits, character height: 14mm
-----------------	---

(3) P2 option

Preset	Output method	PhotoMOS relay a contact (×2)		
	Maxima una ratina	AC140V	0.12A (resistive load)	
output	Maximum rating	DC30V	0.12A (resistive load)	

(4) Al, AV3, AV4, AV5 options

	Maximum resolution	4000				
	Response time	Approximately 50 ms (output change 0 → 90% arrival time)				
Odipat	Temperature characteristic	±100ppm/°C				
output	Accuracy	$\pm 0.3\%$ of the displayed value F. S. (23°C)				
Analog		(AV5) DC0-10V Load resistance: $2k\Omega$ or more				
	Output signal	(AV4) DC0-5V Load resistance: 2kΩ or more				
		(AV3) DC1-5V Load resistance: $2k\Omega$ or more				
		(A I) DC4-20mA Load resistance: 500Ω or less				

(5) Boption

	Output format	All digits parallel		
	Output method	NPN open collector		
BCD	Output timing	TI signal (every display update)		
output	Maximum rating	DC30V 10mA		
	TI signal	Outputs with a width of about 25 mg whan wadeting do		
	(take-up inhibition)	Outputs with a width of about 25 ms when updating data		

(6) Bloption

	Input format	All digits parallel
BCD	Input method	NPN open collector
	Input timing	Every calculation cycle
input	Maximum rating	Load current about 3mA
	Latch signal	Prohibition of data import

(7) F, F2(W), V3, N, L1 options

(1) 1 1 2 (1) 1 2 (1) 1 3 2 1 3				
		(F) Voltage pulse input		
		LOW: 2V or less HI: 3.8-30V		
		(F2(W)) Current modulation pulse input		
Compar		LOW: 8 mA or less HI: 15-20 mA		
Sensor	Input signal	(V3) Tacho-generator signal input		
input		AC 0.8-80Vp-p 3kHz or less		
		(N) Sine wave input		
		AC50mV-20Vp-p 3kHz or less		
		(L1) Line receiver 1-phase (A/ \overline{A}) input		

(8) HI option

Sensor		(H I) High-speed pulse input
_	Input signal	(NPN open collector pulse/voltage pulse/line receiver input)
input		Response frequency : 0.01 Hz - 120 kHz (duty 50%)

(9) S24 option

Sensor				
power	Sensor power supply	(S24)	DC24V (±10%) 60mA	
supply				


(10) DC, K, C, DM, DM-CB options

	Rated power supply voltage	(DC)	DC12-24V (allowable range ±10%)
	Color	(K)	Black
Others	Terminal block cover	(C)	Terminal block cover attached
		(DM)	Stationary case attached
	Stationary type	(DM-CB)	Includes stationary case and 3-core
			cable for stationary case (for AC100V)


3. Mounting meter

How to mount meter

Cut the panel to insert the meter from the front. 1.



2.



Please push the Fitting for fixing the body. Into a right and left both sides of the meter.

Fig.3-2

Driver Fitting for fixing the body Fig.3-3


Slide in the rear side (terminal stand side) as for the fitting for fixing the body. It turns a screw by the driver.

The meter is fixed (right and left both sides)

<Caution>

- 1. Please install it horizontally.
- 2. Fit the body on to a panel 1.0-4.0 mm in thickness.
- 3. Please do not tighten the screw of the mounting bracket too much. (The case might be damaged when tightening too much.)
- 4. When you mount the machine, please provide a space of at least 20mm from the wall in the direction of up and down, right and left and rear (terminal stand side).

4. Names and functions of components on front



①Display unit (A to E)

Measurement state: Measurements are displayed.

Setting state: When the mode is set, it displays it as follows.

A · · · · Mode No. is displayed.

B-E··· Mode items such as the converted value, etc are displayed.

: When the preset output is set, the value input now is displayed.

: When the teaching function is set, the value set now is displayed.

2-6Preset output lamp

Measurement state: When the preset output is output, it lights.

Setting state: When the preset output is set, OUT1-4 that is setting it now is displayed.

6, Teach input display lamp

Measurement state: When Mode No.0 BC is "02"-"07" (ratio measurement), the measurement

display switch of Ratio measurement (A and B input lamp is turned off)/

A input measurement (A input lamp light.)/

B input measurement (B input lamplight.) can be done.

Setting state: The set A input measurement or B input measurement lamp lights when the teaching function is set.

8Hold display lamp

Hold input function is set in Mode No.7 B. (Refer to P.27)

When the hold input of the terminal stand is turned on, and the holding operation is done, it lights.

Mode key (Mode)



Measurement state: It enters the mode setting state if Mode key + Shift key are pushed for 2 sec. or more.

> : It enters the preset output setting state if only Mode key is pushed for 2 sec.or more.

Setting state: When the mode is set, the mode number is raised. When the preset output is set, OUT1-4 is changed.

10 Up key



Setting state: When each setting it, the numerical value of a set digit is raised.

① Down key

Measurement state: When this key is pushed for 2 sec. or more, the state of the mode protecting is displayed. (Refer to P.34 Mode protect function)

Setting state: When each setting it, the numerical value of a set digit is lowered.

12 Shift key

Measurement state: When Mode No.O BC is "OO" (A input measurement) or "01" (B input measurement), The teaching function works. (Refer to P.35 Teaching function)


Setting state: When each setting it, a set digit is shifted to a right digit.

(3) Enter key (ENT)

Measurement state: When Mode No.0 BC is "02"-"07" (ratio measurement), the measurement display switch of Ratio measurement / A input measurement / B input measurement can be done.


Setting state: When the mode is set, and the preset output is set, a set value is registered, and it returns it to Measurement state

(14) Reset key (RST



Setting state: When the mode is set, and the preset output is set, a set value is not registered, and it returns it to Measurement state.

Fig.5-1




- /! < Caution >
 - For safety, wiring should be performed by a person who has specialized technology such as electrical work and electrical wiring.
 Also, be sure to turn off the power before wiring the electric wires.
 Please shut off the power when electrical wiring.
 - 2) Power supply confirmation
 - Confirm the specification of the AC power supply type and the DC power supply type well.
 - DC power supply type notes the polarity.
 - 3) Wire correctly after often confirming the terminal stand label.
 - 4) The wiring technique is different depending on the kind of the sensor. Wire correctly referring to the connection diagram (P.9) and the manual of the sensor. The sensor and the meter might break down when connecting it by mistake.
 - 5) Do not use the sensor power supply for the usages other than the sensor.
 - 6) Tighten the screw of the terminal stand surely.
 - 7) Do not touch the terminals while power is being supplied. There is a risk of electrical shock.


A. Tacho-generator / Sine wave

Fig.5-2

B. Pulse output 2-wire type sensor

Fig.5-3







C. Ground contact output sensor

Fig.5-4

D. Line driver encoder

Fig.5-5







E. Pulse output 3-wire type sensor

Fig.5-6

F. Current pulse input (3-wire pulse sensor)

Fig.5-7





G. Current pulse input (2-wire pulse sensor)





Fig.5-8

NOTE

- When mis-counting by the chattering of the having point of contact input, (Relay etc.) Connect the electrolytic capacitor with terminal stand 6-7 (A input) and 6-8 (B input) according to the frequency.
- When mis-counting because of the noise etc, Connect the film capacitor with the same terminal according to the width of the input frequency and the noise.

1) NPN open collector pulse input

Fig.6-1



2 Voltage pulse input

3 Reset • Hold input






Fig.6-4

4 Tacho-generator signal input/Sine wave signal input

⑤ Line driver input

Fig.6-5





Sensor input, and relationship of the sensor input response is shown in Table 7-1.


Table.7-1


	B.	IN	A.	IN	B.IN	A.IN	
	1	2	3	4	5	6	OFF⇔ ON
Input frequency 0.01Hz - 50Hz LOW	ON	OFF	OFF	ON			⊢ ■
Input frequency 0.01Hz - 1kHz MID	OFF	ON	ON	OFF			
Input frequency 0.01Hz - 10kHz HI	OFF	OFF	OFF	OFF			
Input frequency 0.01Hz - 120kHz 💥	OFF	OFF	OFF	OFF			
NPN open collector input					ON	ON	
Voltage pulse input					OFF	OFF	


Option(H I) type

When a sensor optional input is not specified, sensor input is "NPN open collector", and Sensor input response is "H $\!$ I".

Fig.7-1







Please recommend to take notes of the value setting of each mode.

RSID: Returns without registering.

If the specifications desired by the user are requested prior to shipment, the meter will be set these settings. Other wise, the regular factory settings are shown below.

Value setting of each mode

Table.9-1

value settil g 01 each 1110de 1 able.5							JIC.J 1	
Mode No.		Initial:	setting	5		No	tes	
А	В	С	D	Е	В	С	D	Е
0.	0	0	2	1				
1.	1	0	0	0				
2.	3	0	0	2				
3.	1	0	0	0				
4.	3	0	0	2				
5.	1	0	0	0				
6.	_	0	2.	Ο	_			
7.	0	_	0	0		_		
8.	0	0	0	0				
9.	0	0	0	0				
Α.	0	0	0	0				
b.	0	0	0	0				
C.	_	1	0	_	_			
d.	1	0	0	0				
E. (B)	_	_	_	0		_	_	
F. (BI)	0	_	0	1		_		

Presetting output set value

Table.9-2

OUTPUT No.	А	В	С	D	Ε	Α	В	С	D	Е
OUT1	9	9	9	9	9					
OUT2	9	9	9	9	9					
OUT3	9	9	9	9	9					
OUT4	9	9	9	9	9					

<

Throw power supply in with pressed to initialize the settings.

After the initialization, the set values will be as shown in Table 9-1, Table 9-2. Mode protect function are also cleared.

/! <Caution>

**Since an initialization changes all existing setting values to the initial setting values, be sure to record all the setting values before an initialization.

In case the computer froze when unusual functioning occurred with the normal operation, initialize according to the above procedure and set the desired value again.

\ll 1. Operating method (the mode setting) \gg

When doing mode setting, please operate as follows.

Table.10-1

Operating key	Indication	Procedure
Model H Model key Shift key	A B C D E O. O O 2 1 Mode No. Data value	While pushing down Mode key and Shift key for 2 sec or more. "O" appears in displays A ,the value setting for Mode No.O is shown.
Up key	A B C D E O. 0 0 2 1 ↑ O-9	Up key changes the flash figure. Each time the key is pressed, a flash figure is rising up. (0→1→・・→9→0→1・・・) *In Situation, doesn't indicate by a set ting figure, up to nine.
Down key	A B C D E O. 9 0 2 1 1 9-0	Down key changes the flash figure. Each time the key is pressed, a flash figure is down. $(9 \rightarrow 8 \rightarrow \cdot \cdot \cdot \rightarrow 1 \rightarrow 0 \rightarrow 9 \cdot \cdot \cdot)$
Shift key	A B C D E O. 9 0 2 1	A figure of flash indication is shifted. Each time the key is pressed, a flash figure is shifted, to the right.
(Mode) Mode key	A B C D E 1. 1 0 0 0 ↑ 0-9, A,b,C,d,E,F	The Mode No. is changed. Each time Mode key is pressed, the Mode No. is rising. (Rise) $(0\rightarrow 1\rightarrow \bullet \bullet \bullet \rightarrow F\rightarrow 0\rightarrow 1\bullet \bullet \bullet \bullet)$ All modes are "0-F". When the Mode No. reached "F", return to "0".
ENT Enter key		After adjusting the setting, use Enter key to register it. It returns to the measurement display after a set value is registered.
Reset key		It returns to the measurement display without registering a set value.


/!\<Caution>

**Please make the mode protect function "L-off" at the mode setting. If it's a condition of "L-on", it can't be changed.

About the contents of the mode protect function, please refer to "11.Mode protect function".


Mode No.	Measuring types, Measurement unit, Display decimal point
Ο	A B C D E O. O O 2 1 Display decimal point setting O: O 2: 0.00 1: 0.0 3:0.000 Measuring unit O: hour 1: minute 2: second 3: hour-minute 4: minute-second 08,13-15 alone can be used.
	Measuring types O0: A-input: speed, rotation, flow rate measurement O1: B-input: speed, rotation, flow rate measurement O2: Ratio measurement (absolute ratio measurement) B/A×100 O3: Ratio measurement (error ratio measurement) (B-A)/A×100 O4: Ratio measurement (difference measurement) A-B O5: Ratio measurement (density) B/(A+B)×100 O6: Ratio measurement (sum measurement) A+B O7: Ratio measurement (sum measurement) A+B O7: Ratio measurement (sum measurement) (A+B)/R or (A-B)/R O8: Passing time measurement O9: Shot speed UA (2 sensor one direction speed) 10: Shot speed UB2 (1 sensor one direction speed) 11: Shot speed UB2 (1 sensor reciprocal speed) 12: Shot speed UC (2 sensor reciprocal speed) 13: Cycle-timer measurement 14: Stop watch A 15: Stop watch B NOTE: Upon setting 16 - 19, same operation as with 00 is mode. Option: Al /AV3-5 In analog output, The real-time output functions only when I set Mode No,0 "00" (A input) or "01" (B input) or "08" (Passing time measurement). Otherwise, set it in 1 (Synchronizes for the display). When use analog output, the measurement unit choose O(hour) or 1 (minute) or 2(second).
(00)	(Ratemeter) When I use it in Ratemeter (speed, rotation, flow rate), choose this mode. Choose "00" (A input) or "01" (B input).

(Ratio measurement) absolute ratio measurement • • B/A×100 (02) (03) (04)(05) sum measurement · · · · · A+B (06) (differential rate measurement) There is a signal of two kinds of number of revolutions of A and B, The 2 signals are input, and the following calculation is considered to be it, Furthermore, analog output and the preset output are possible for indication value data. Deceleration ratio"R" R: 0.1~999.9 ON/OFF (reverse-rotation input ON) 1) Calculation type 1A and B turn in the same direction: (A-B) / R(Terminal stand 2-3 is a state of OFF) (07) \bigcirc A and B turn to the opposite direction: (A+B)/R(Terminal stand 2-3 is a state of ON) 2) Setting method ①Set scaling of A input and B input : (Mode No.1-4) 2 Deceleration ratio (R) setting: (Mode No.5) 3Sampling time: (Mode No.6) 4Setting of the preset output (Std.): (Mode No.8, 9) (Option): (Mode No.A. b) Setting of the analog output. (Option): (Mode No.C, d) 6Setting of the reverse-rotation input : (Mode No.7) 3) Operation explanation ①A input lamp lights up when I push (N) during a measurement, and number of revolutions of the A input is displayed. B input lamp lights it up when I push (BT) once again and displays number of revolutions of the B input. A input lamp and B input lamp turn off the light when I push (N) once again, and differential rate is displayed. 2 Reverse-rotation input is shown terminal stand 2-3 when short-circuit. When, in this state, I operate the above "①", Number of revolutions and differential rate of each input are displayed. Perform the A input with open collector signal or no voltage point of contact signal



(13) (Cycle-timer measurement)

- 1) When sensor input A does ON, it is started time measurement.
- 2) It is displayed measurement time when sensor input did ON again, and time measurement is started again.
- 3) The time measurement is suspended between ON sensor input B.
- 4) When ON did reset input, indication is returned to 0, and the time measurement stops.




When blackout and power supply OFF are considered to be it when they use this function, indication measuring returns to 0.

(14) (Stop watch A)

- 1) When sensor input A does ON, a measurement is started and displays it at the same time. When sensor input A does ON once again, a measurement is stopped.
- 2) Sensor input B works as input in a lap time. When ON is considered to be it during time measurement, the indication is performed hold of, but can continue measuring the time. Then, When B sensor input does ON, it is gone back up for time measurement indication. The second input is not B sensor, and, in the case of A sensor, the time

until the point in time is displayed, and time measurement is stopped.

3) When ON did reset input, indication is returned to 0, and the time measurement stops.




When blackout and power supply OFF are considered to be it when they use this function, indication measuring returns to 0.

(15)

(Stop watch B)

- 1) When sensor input A does ON, a measurement is started and displays it at the same time.
- 2) When ON does B sensor next, a measurement stops.
- 3) When reset input is performed ON of, indication and the internal counter are corrected to 0 and are stopped time measurement



$^{\prime !}ackslash$ < Caution >

When blackout and power supply OFF are considered to be it when they use this function, indication measuring returns to 0.

Measuring unit

- 1) Choose any Measuring unit, But, when I chose "00" (A input) or "01" (B input), "03-07" (Ratio measurement), "09-12" (Shot speed).
 - 3: hour-minute becomes 1: minute.
 - 4: minute-second becomes 2: second
- 2) When it is chosen "08" (Passing time measurement), " $13\sim15$ " (Cycle-timer, Stop watch A and B) by a measuring types,
 - 3: hour-minute and 4: minute-second are selectable.

When it is chosen Measuring unit above, please refer to P.36 (caution below) for preset output.

Display decimal point setting

Please set a position displaying a decimal point.

But the decimal point is ignored when I set 3: hour-minute or


4: minute-second with Mode No.0 "D: Measuring unit".

NOTE

This decimal point setting links setting of the preset output.

	
Mode No.	A-input : Setting of scaling data
1	A B C D E 1. 1 0 0 0 Scaling data: 0001 – 9999 (Do not set 0000)
	Please set the pulse rate (scaling data) of the sensor. 4 digit of numerical value to set with this mode, and please input Exp.value of Mode No. 2. Then $1 \times 10^{-9} \sim 9999$ " can set the magnification per 1 signal. Measuring types: 08(Passing time measurement), set it in unit "mm/p" Measuring types: 09~12(shot speed), set the distance between the sensor.
	 (Ex.) Using a flow sensor which emits 1 pulse per 1.234mL, the cumulative total flow in liters can be expressed using the following conversion. 1.234mL → 0.001234L → 1234 × 10⁻⁶
	Scaled to the desired unit (L) 4 digits (Scaling data) Exp. Value (exponent) A B C D E Mode No.1 1. 1 2 3 4 A B C D E Mode No.2 2. 6 * * *
	The above is based on the example of flow rate measurement, while for examples of conversion value, refer to next page. For ratio-measurement, sensor is connected to A and B for each 1 piece, then, set Mode No."3"and"4".

Example	Arithmetic expression
Arithmetic expression	In case of "Revolution" Scaling data=1 revolution/pulse In case of "Speed" Scaling data=Amount of transfer/pulse In case of "Flow" Scaling data=Flow rate value/pulse
(Ex.1) Revolution	Factor — 1 revolution/1 pulse = 1 Exp. value "Mode No.2" O001×10-0 or 1000×10-3 Mode No.1" ** Please register scaling data of "the left side or "the right side". Sensor The right side can be adjusted slightly.
(Ex.2) Revolution	Factor — 1 revolution/30 pulse=1/30=0.033333 3333×10 ⁻⁵ Mode No.1" — Exp. value "Mode No.2" **Please register scaling data of "Mode No.1" and "Mode No.2".
(Ex.3) Speed	Factor → The speed of "Drive roller; 100 φ" is indicated. Scaling data=Amount of transfer/pulse Scaling data=100×π/30÷10.47197mm In case of "mm/min" 1047×10 ⁻² In case of "cm/min" 1047×10 ⁻³ In case of "m/min" 1047×10 ⁻⁵ The number of gear tech30 "Mode No.1" Exp. value
(Ex.4) Flow	Factor 7.692mL/pulse Scaling data=Flow rate value/pulse In case of "mL/min" 7692×10 ⁻³ In case of "L/min" 7692×10 ⁻⁶ Sensor "Mode No.1" Exp. value



(Ex.) The magnification per 1 signal assumes it 0.1234, and the moving average zeroes indication by invalidity five seconds after the last input signal.


A B C D E Mode No.1


1. 1 2 3 4 B~E: (1234×10=4=0. 1234)

A B C D E Mode No.2

2. 4 0 0 4 B: 4 (Exp value input mentioned above) CD: 00 (Moving average invalidity) E: 4 (It is indication "0" 5 sec. after the last input signal)


Mode No.	B-input : Setting of scaling data
3	A B C D E 3. 1 0 0 0 Scaling data: 0001 – 9999 (Do not set 0000)
	Setting method same as Mode No.1 (A-input: Setting of scaling data)







Mode No.	Sampling time
6	A B C D E 6. 0 2. 0 Sampling time: 00.0 - 99.9 seconds (00.0 shall be the real-time display.)
	For sampling time, input signal is measured with its set time, and its mean value is calculated and displayed, then, use it for preventing the flashing or for stabilizing the display. Accordingly, renewal shall be made by averaging the display for each set time.
	With the setting of 00.0, display is made for each pulse. It is effective with about 1 pulse / seconds , whereas, pay attention to the fact that the faster pulse induces more flicker.
	When change sampling time, and after former sampling time was over, it becomes effective


Mode No.	Hold input function setting, display blank, lowest digit display
7	A B C D E 7. 0 0 0 Lowest digit display 0: Real 1: Fixed at 0 2: 0 or 5 Display blank 0: Normal display 1: Blank display 1: Blank display 1: Peak hold 2: Bottom hold 3: Hold 4: Reverse-rotation input (differential rate measurement) (Hold input function setting) Set a function when ON(short) did terminal stand 2 – 3 0: No use Hold input is invalid. 1: Peak hold Between ON, it updates a highest value indication level while blinking. 2: Bottom hold Between ON, it updates a smallest value indication level while blinking. 3: Hold Between ON, It displays a current value while blinking. 4: Reverse-rotation input (differential rate measurement) It functions as Reverse-rotation input. (This function becomes invalid other than differential rate measurement)
	(Display blank) When I set it to 1, A measured value (7 segment LED) and each lamp display it and do not turn on. (But preset put lamp OUT1-4 is excluded) (Lowest digit display) The form of indication for the least significant digit (digit on the right end) is selected. O: Real • • • • • • Synchronized at the sampling time. 1: Fixed at O • • • • Always, "O". 2: O or 5 • • • • • • 0-4 are expressed as O, and 5-9 as 5.





Mode No.	OUT2: Preset output (open collector output)
9	A B C D E 9. 0 0 0 0 Output mode 0: Comparison 5: 100 ms (1 shot) 1: Hold 6: 250 ms (1 shot) 2: 10 ms (1 shot) 7: 500 ms (1 shot) 3: 20 ms (1 shot) 8: 1 sec (1 shot) 4: 50 ms (1 shot) 9: 2 sec (1 shot) Up limit / down limit selection 0: Up limit 1: Down limit 2: Down limit (delay) Judgement output prohibition time: 00 - 99 sec
	The setting method same as Mode No."8" OUT1
	(Ex.) With the judging output inhibition time 30 seconds, down limit is selected, and output-mode 50 ms (1 shot) is selected, then, setting is made as follows. ABCDE 9.3014














11. Mode protect function

When the mode protect function is made effective, and operation is invalid by mode setting. Therefore the set value can't be changed.

In an early stage, the mode protect function is invalid.

When doing the mode protect function setting, please operate as follows.

«Operation of the mode protect»

Table.11-1

Operation key	Indication	Procedure
Down key	A B C D E L — o F F (The mode protect: present)	Press the key for 2 sec. or more. The present mode protect state is displayed. (The regular factory setting is "L-off".)
Down key	A B C D E L — <u>o n</u> (The mode protect : change)	Keep pressing for 8 sec as it's continuously, the state of mode protect is changed. X" OFF → ON" or "ON → OFF"
Down key		It usually returns when jis stopped being pressed.

/! < Caution >

*The preset value setting and the offset value setting always can be changed.

%The mode protection function becomes "OFF", when it's initialized.

What is the teaching function?

Change the current indication level to any value. (setting automatic as for the scaling data.)
[Ex.] when input frequency 100Hz is displayed as 200.0rpm, for changing the display value from 200.0 to 180.0, converted value may be changed, whereas, upon setting "180.0" by the teaching function, 180.0 is automatically displayed. At this time, converted value is automatically re-written by reverse calculation from the set value as 180.0

Converted Scaling data — Automatically re-written converted Scaling data — Converted value 3333 — Converted value 3000 — EXP 5

Table, 12-1

Operating key	Indication	Procedure
Shift key	A B C D E 2 0 0. 0	Push of for 2 sec., or more. In the case of A input measurement, A input lamp blinks. In the case of B input measurement, B input lamp blinks.
Shift key	A B C D E 0→2→0→0→0	A figure of flash indication is shifted. Each time the key is pressed, a flash figure is shifted, to the right.
Up key Down key	A B C D E O 1 8 0. 0	Push this key for changing the value flashing. One figure moves up and down every time it pushes once.
Enter key		After input of the desired value from the data value 200.0, push (ENT). Upon pushing this (ENT) key, the measuring mode returns, and the converted Scaling data and EXP value can be re-written.
Reset key		It returns to the measurement display without registering a set value.

(The decimal point position links setting of Mode No.O "E" Display decimal point setting)

$\cancel{!}$ < Caution >

- This teaching function can set only ratemeter (speed, rotation, flow rate) of A-input and B-input. (Need to set in Mode No.O 'BC' OO or O1)
 When it is other measurement types, teaching function becomes invalid.
- Do not make this operation at time of stop or low turning (Frequency).

13. Calling up and modifying the preset value setting

Set the value to pre-set of the preset out by the following method.

The set range is "-9999" - "99999"

In addition, please refer to Mode No.8-b (P.28-30) for the setting of the preset output.

Table 13-1

		Table.13-1
Operating key	Indication	Procedure
Mode key	A B C D E	Push Mode for 2 sec., or more. "OUT1" lamp lights up, and a current preset value is displayed.
Shift key	A B C D E 9→9→9→9→9 1 ● 20 30 40	A figure of flash indication is shifted. Each time the key is pressed, a flash figure is shifted, to the right.
Up key Down key	A B C D E 9	Push this key for changing the value flashing. One figure moves up and down every time it pushes once.
Mode)	A B C D E 9 9 9 9 9 10 2• 30 40	Push Mode key. The OUT1 lamp shifts to OUT2 lamp. OUT2 lamp lights up, and a current preset value is displayed and can set it.
Mode)	A B C D E 9 9 9 9 9 10 20 3● 40	Push Mode key. The OUT2 lamp shifts to OUT3 lamp. OUT3 lamp lights up, and a current preset value is displayed and can set it.
Mode)	A B C D E 9 9 9 9 9 10 20 30 4●	Push Mode key. The OUT3 lamp shifts to OUT4 lamp. OUT4 lamp lights up, and a current preset value is displayed and can set it.
Enter key		After adjusting the setting, use FNT to register it. It returns to the measurement display after a set value is registered.
RST Reset key		It returns to the measurement display without registering a set value.

(Decimal point of the display value is inter connected with Mode No.O - E.)

/! < Caution >

- In case selecting the time-measuring time (Mode No.0 08, 13, 14, 15) and the measuring unit (hour-minute) (minute-second), be sure to set the value of display unit C to "0".
- When P2 option is not equipped with, OUT3 and OUT4 are not output. (only a lamp turns on.)



The analog output (Al/AV3-5) range is adjusted correctly at a factory.

Please do not touch except necessity.

/!\<Caution>

When adjusting the analog output, the customer will not be able to return it to the original state without an accurate measuring instrument, so be careful when performing it.

«Adjustment method»

- 1. Power on the Mode being pressed to put the instrument into the test mode.
- 2. Press the (Mode) until the analog output test "Ad" appears.
- 3. Please coordinate the ZERO volume with the SPAN volume to become the following output voltage/current. (Please adjust it from the ZERO volume by all means.)

Voltage output (AI) type unit

Indication	Output current	
0	4mA	Turn the zero volume to adjust
100	20mA	Turn the span volume to adjust

⁽X Repeat the procedure several times for fine adjustment.)

Voltage output (AV3) type unit

Indication	Output voltage	
0	1 V	Turn the zero volume to adjust
100	5 V	Turn the span volume to adjust

^{(*} Repeat the procedure several times for fine adjustment,)

Voltage output (AV4) type unit


Indication	Output voltage	
0	OV	Turn the zero volume to adjust
100	5 V	Turn the span volume to adjust

^{(*} Repeat the procedure several times for fine adjustment.)

Current output (AV5) type unit

Indication	Output voltage	
0	OV	Turn the zero volume to adjust
100	10 V	Turn the span volume to adjust

^{(*} Repeat the procedure several times for fine adjustment.)



15. Adjusting the tacho-generator signal, sine wave signal input (Option:V3/N)

/!\<Caution>


The input (V3, N) range is adjusted correctly at the factory. Please do not touch except necessity.

V3-type: Tacho-generator signal input AC 0.8 to 80V(P-P) N-type: Sine wave signal input AC 0.05 to 20V(P-P)

«Adjustment method»

The sensitivity adjustment volume is seen from a round hole on meter left side. Please adjust it while seeing the display.

Fig.15-1 Adjustment volume



- 1. The Binary Coded Decimal code is the NPN opening collector pulse output, In addition, it becomes all figure parallel output,
- 2. The output of data becomes the output for a measurement chosen by a measurement operation method. I output it in sync with a measurement.

 (It is not output by the indication of the hold state.)
- 3. The output logic of data is modifiable. (Please refer to P.32 Mode No. E)

Output logic (positive) : The state that an emitter does conduction with the collector of the output transistor when data output it


Output logic (negative): The state that an emitter does not conduction with the collector of the output transistor when data output it

4. When I take in data because TI (take-up inhibition) signal is output at the time of data update, TI signal please go at the time of OFF.

The logic of the TI signal is modifiable, too. (Please refer to P.32 Mode No. E)


(Pin assignment of the BCD output (The meter side is D-sub 37pin female))

Fig.16-1




(Circuit diagram for BCD output)

Fig.16-2



(Timing chart of output)



- 1. The Binary Coded Decimal code is the NPN opening collector pulse output. In addition, it becomes all figure parallel output.
- 2. The input logic of data is modifiable. (Please refer to P.33 Mode No. F)

Hi active : Each pin of input data is in condition to open with GND.

Negative sign only: Each pin of input data is in condition to short with GND.

Low active : Each pin of input data is in condition to short with GND.


Negative sign only: Each pin of input data is in condition to open with GND.

3. Latch input • • I prohibit the uptake of data. Therefore, I hold data when I wore a latch even if the later input data change. When I want to update data, I turn off a latch (Uptake possibility) and take in data, and ON does a latch (Uptake prohibition) again.

Latch(Short): When Latch(Pin 37) and "GND" are in a short state, I prohibit the uptake of data. Latch(Open): When Latch(Pin 37) and "GND" are in a open state, I prohibit the uptake of data.


(Pin assignment of the BCD input (The meter side is D-sub 37pin female))

Fig.17-1



Taking of data (Input prohibition with "open")

Fig.17-2







Fig.18-1



Terminal screw: M3.5 Terminal width: 7mm

The terminal stand cover is "C" option

Fig.18-2




Fig.19-1 Terminal stand for power supplies Terminal stand <Terminal stand for power supplies> F.G. ____\AC power supply \oplus DC power supply \oplus ① ō \oplus (+)<l \oplus 8mm Handle \oplus \oplus Meter terminal stand *Please use the attached AC cord in AC125V or less. The wiring to a meter takes off the screw of the case and performs it. To a terminal stand as for the power supply wire for power supplies 250 The signal line connects it to a meter terminal stand. 3 core AC cord 2m Tilt stands < About a wiring method> <CB option accessories> 2P Conversion Screw (4pcs.) adapter Power switch Reset switch Fuse holder Meter POWER N 0 0 150 <Rear view> Wiring drawer hole Terminal stand power supplies 140 11 10 161 (Unit:mm)

When influence of noise occurred, please be careful about the following.

When doing a blackout and a malfunction by influence of noise, please be initialized. (Refer to P.14)


Please take notes of the value setting of each modes.

If it becomes normal, please take the following measure.

And please setting it once again.

- (1) Do not share the power supply with a power line directly.


 (When I share a power line, please use an isolation transformers)
- (2) Please use 3 cores of shielding wire for a sensor, separate as much as possible from a source of noise.
- (3) Please avoid a source of noise (power supply line and inverter), make it as short as possible. After that, please install a sensor code.
- (4) A great many noises may be included in F.G. Line of the device. In this case you should not tie F.G. of the meter.




(6) The manner of the sensor cord installation.

When there is a power supply line near the sensor cord, a surge and noise are influenced.

Therefore, install a sensor cord independently or for 50 cm or more.



(7) When being affected than other equipment, please use a spark killer like Fig.20-4 and take a measure.



(8) If there is an unclear point, please even consult with use about a dealer or us.

When abnormality occurred, please check it as follows.

No.	Problem	Checking point	Solution
1	Display does not appear at all.	→ Has it connected with the rear terminal correctly? ↓ ↓ → Does a sensor power supply short-circuit? (Or it is an overcurrent)	→ Connect correctly according to "Connecting terminal boards (Refer to P.8) → Sensor specifications confirmation. Take off a sensor and check the operation.
			→Initialize (Refer to P.14) When display still does not appear, have it serviced.
2	Unusual • LED lighting, key • switch operation, • preset output, • analog output	→Check with the test mode, (Refer to P.12)	→Initialize (Refer to P.14) When it still does not resume normal status, have it serviced.
3	Remains at "O"	→Is the setting for each mode correct? ↓ →Is the sensor input normal? ↓ ↓ →Is the distance of the sensor normal? ↓ ↓ →Is the input system of this meter suitable for the output signal of the sensor?	→Check the setting again. (Refer to P.16-P.33) →Check the connection of the sensor (Refer to P.9). Check with the test mode (Refer to P.12). →The sensor lamp flash is confirmed. A sensor is tested. "ON/OFF" When it still does not resume normal status, have it serviced.
4	Indicator is flashing "99999" . (Error indication)	→Check whether the scaling is not too large →Influence of noise.	→Change the scaling data. (Refer to P.17-19 for Mode No.1-4) →Noise countermeasure (Refer to P.43)

No.	Problem	Checking point	Solution
5	Indication is not stable	→It is sometimes displayed smaller than a real value. ↓ →It is sometimes displayed more greatly than a real	→Detection error of the sensor. check the accuracy of the sensor when there is little quantity of detection
		∨alue. ↓ ↓	→Noise countermeasure (Refer to P.43)
		↓ ↓ ↓ →Because the movement of the measurement thing fluctuates, the signal of the sensor sways	 →When it is caused by the chattering such as relays, Please attach a capacitor to the sensor input terminal. →Lengthen sampling time (Refer to P.26) When it still does not resume normal status, have it serviced.
6	Indication goes out. An indication level becomes than double.	→Influence of the spark noise with a relay or the electromagnetic valve	→Noise countermeasure (Refer to P.43)
7	Other problems		→Have it serviced.

■EMC standard (EN61326-1:2021)

Emission

EN55011 Group 1 Class A

This product complies with EMC standards for industrial environments.

When used in a residential or light industrial environment, it may cause electromagnetic interference to other equipment.

Immunity

EN61000-4-2, EN61000-4-3, EN61000-4-4, EN61000-4-5, EN61000-4-6, EN61000-4-11

*Analog output is allowed up to ± 1 mA for 4-20mA during testing.

This product complies with EMC standards for industrial environments.

Users should pay particular attention to the electromagnetic immunity listed below.

- Power supply quality Electrostatic discharge Radiated noise Conducted noise
- Magnetic field noise
 Surge noise

U UINICS CO.,LTD.

Head Office / Technical inquiry

TEL:+81-72-274-6001 FAX:+81-72-274-6005

123-1, Kami, Nishi-Ku, Sakai-shi, Osaka, 593-8311 Japan

Tokyo Office

TEL:+81-3-5256-8311 FAX:+81-3-5256-8312

URL: https://www.uinics.co.jp Scan the QR code to access the website.



Please note that the communication costs shall be borne by the customer.

**All specifications may be changed without notice.